



ASHBY-MF CORRECTION

There was an error on the Ashby-MF price sheet and letter that was sent this week. The bolt-on ash pan cannot be removed from the Ashby-MF. The ash pan is needed to drop the clinker that is created when corn is burned. Enclosed you will find a copy of the revised price sheet. The surrounds that were needed for the Ashby without the bolt-on ash pan have been removed from the price page. If you have any questions, please call us at 800-709-7288. We are sorry for the inconvenience.

August 21, 2009